


# Telecommunication Tower Case Study

Equipment:  
100 ton Crane  
Winch Tractor & Trailer

Challenges:  
Tight Area  
Close Proximity to Transmission & Distribution Lines

Cleared bush from site for access. Worked with communication company to disassemble tower, lay down & load on trailers. Hauled off site and stored for a month while new site was being prepped. Transported to new site and reassembled. Job - 45m monopole removal & Reassemble. Being relocated for development of SW Stony Trail Expansion.



Proudly Serving  
Customers  
Throughout  
Western Canada

Dispatch  
24Hrs  
403-888-1255  
dispatch@mcintyrecrane.ca

Dallas McIntyre  
President  
403-771-0761  
dallas@mcintyrecrane.ca

